



Jefferson Lab Alignment Group

Data Transmittal

TO: S. Chandra

DATE: 05 Oct 2006

FROM: Tom Singleton

Checked:

: P1078

DETAILS:

The results of the topographic survey of the storm drainage as-found elevations around buildings 85, 87 and 89 are attached. The civil network was used and all elevations are based on that datum. All elevations are to the ground surface.

Attached is a sketch showing the locations of all points surveyed. A section of notes is included for a more detailed report concerning the drainage pipes type, size (diameter and length), flow calculations, flow direction and existing conditions.

<u>Key</u>	<u>Description</u>
T B	Top of Bank
E P	Edge of Bank
T W	Top of Walk
CLD	Centerline of Ditch
INV	Invert of Pipe (elevation at the flow line)